

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Data

No

0.0

1.3

Yes

Yes

Intersection ID: 18238 Main Street: QUEEN ANNE RD **Cross Street: S TRYON ST** Location: N/A ADA ID: AA4EAB6B9B0A Curb Cut Type: MedianRefuge2 Initial Pass/Fail: Pass **Overall Compliance: Yes Severity Score:** 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

1.6 Yes

54.0

No

To SE

Data Compliance

Yes Gutter 1 Ponding?

Gutter 1 Slope (%) Gutter 1 X Slope (%)

DWS 1 Provided?

DWS 1 Contrast?

96.0 Yes Gutter 1 Lip Ht (In)

Description

Description

Refuge 1 Length (In)

Refuge 1 Width (In)

Refuge 1 Slope (%)

Refuge 1 X Slope (%)




Possible Solutions: N/A Surveyor Notes:

N/A

PROW/ADA:

N/A

Total Cost:



Compliance

X Walk 1 Width (In) N/A DWS 1 Length (In) 24.0 0.2 Yes DWS 1 Full Width? Road 1 Slope (%) Yes Road 1 X Slope (%) 1.9 Yes DWS 1 Offset (In) 0.0 54.0 Yes Refuge 2 Length (In) Gutter 2 Ponding? No Refuge 2 Width (In) Gutter 2 Lip Ht (In) 96.0 Yes 0.0 Refuge 2 Slope (%) Gutter 2 Slope (%) 1.6 Refuge 2 X Slope (%) Gutter 2 X Slope (%) 0.2 Yes 0.2 Painted X Walk2? No Yes DWS 2 Provided? Yes To NW DWS 2 Contrast? X Walk 2 Direction Yes X Walk 2 Width (In) N/A Yes DWS 2 Length (In) 24.0 Road 2 Slope (%) DWS 2 Full Width? Yes Yes DWS 2 Offset (In) Road 2 X Slope (%) 2.6 0.0 Refuge 3 Length (in) Gutter 3 Ponding? N/A N/A Refuge 3 Width (in) N/A Gutter 3 Lip Ht (in) N/A Gutter 3 Slope (%) N/A Refuge 3 Slope (%) N/A N/A Refuge 3 XSlope (%) N/A Gutter 3 XSlope (%) N/A Painted X Walk3? DWS 3 Provided? N/A N/A X Walk 3 Direction N/A **DWS 3 Contrast?** N/A DWS 3 Length (in) X Walk 3 Width (in) N/A N/A N/A Road 3 Slope (%) N/A DWS 3 Full Width? N/A DWS 3 Offset (in) Road 3 XSlope (%) N/A N/A Any Obstructions? Storm Grate/Utility Hazard? No N/A Storm Grate/Utility Type **Obstruction Type** N/A N/A Surface Condition Good





