


# Access Compliance Report

## Public Rights-of-Way

### (Island Curb Cuts)

Intersection ID: 6102	Main Street: UNIVERSITY_CITY_BV	Cross Street: UNIVERSITY_PROFESSIONAL_DR	Location: N
ADA ID: B1B8DBFF69FF	Curb Cut Type: IslandRefuge3	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 36.25	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>	
	<b>Remove &amp; Replace Entire Refuge.</b>		<b>Yes</b>	Refuge 1 Length (In)	<b>93.0</b>	<b>N/A</b>
			<b>Yes</b>	Refuge 1 Width (In)	<b>121.0</b>	<b>N/A</b>
			<b>Yes</b>	Refuge 1 Slope (%)	<b>2.4</b>	<b>N/A</b>
			<b>Yes</b>	Refuge 1 X Slope (%)	<b>3.3</b>	<b>N/A</b>
			<b>N/A</b>	Painted X Walk1?	<b>Yes</b>	<b>N/A</b>
			<b>N/A</b>	X Walk 1 Direction	<b>To W</b>	<b>N/A</b>
			<b>N/A</b>	X Walk 1 Width (In)	<b>116.0</b>	<b>N/A</b>
			<b>N/A</b>	Road 1 Slope (%)	<b>3.3</b>	<b>N/A</b>
			<b>N/A</b>	Road 1 X Slope (%)	<b>2.4</b>	<b>N/A</b>
Surveyor Notes:  <b>N/A</b>			<b>Yes</b>	Refuge 2 Length (In)	<b>93.0</b>	<b>N/A</b>
			<b>Yes</b>	Refuge 2 Width (In)	<b>114.0</b>	<b>N/A</b>
			<b>Yes</b>	Refuge 2 Slope (%)	<b>3.6</b>	<b>N/A</b>
			<b>Yes</b>	Refuge 2 X Slope (%)	<b>5.0</b>	<b>N/A</b>
			<b>N/A</b>	Painted X Walk2?	<b>Yes</b>	<b>N/A</b>
			<b>N/A</b>	X Walk 2 Direction	<b>To N</b>	<b>N/A</b>
			<b>N/A</b>	X Walk 2 Width (In)	<b>123.0</b>	<b>N/A</b>
			<b>N/A</b>	Road 2 Slope (%)	<b>5.0</b>	<b>N/A</b>
			<b>N/A</b>	Road 2 X Slope (%)	<b>3.6</b>	<b>N/A</b>
			<b>Yes</b>	Refuge 3 Length (in)	<b>49.0</b>	<b>N/A</b>
PROW/ADA:  <b>N/A</b>			<b>Yes</b>	Refuge 3 Width (in)	<b>121.0</b>	<b>N/A</b>
			<b>Yes</b>	Refuge 3 Slope (%)	<b>2.8</b>	<b>N/A</b>
			<b>Yes</b>	Refuge 3 XSlope (%)	<b>3.2</b>	<b>N/A</b>
			<b>N/A</b>	Painted X Walk3?	<b>No</b>	<b>N/A</b>
			<b>N/A</b>	X Walk 3 Direction	<b>To S</b>	<b>N/A</b>
			<b>N/A</b>	X Walk 3 Width (in)	<b>N/A</b>	<b>N/A</b>
			<b>N/A</b>	Road 3 Slope (%)	<b>1.6</b>	<b>N/A</b>
			<b>N/A</b>	Road 3 XSlope (%)	<b>2.9</b>	<b>N/A</b>
			<b>Yes</b>	Any Obstructions?	<b>N/A</b>	<b>N/A</b>
			<b>N/A</b>	Obstruction Type	<b>N/A</b>	<b>N/A</b>
Total Cost: <div>             \$             3000.00           </div>			<b>N/A</b>	Surface Condition	<b>Good</b>	<b>N/A</b>

