

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Data

N/A N/A N/A N/A N/A N/A

N/A

N/A N/A

N/A N/A N/A

N/A N/A

N/A N/A N/A N/A

N/A

N/A

Main Street: FREEDOM DR **Cross Street: MARLENE ST** Location: Intersection ID: 9325 N/A **Curb Cut Type: MedianRefuge2** Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: D42B67F794A9 Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Remove & Replace Entire Refuge.

Surveyor Notes:

N/A

PROW/ADA:

N/A

	rieid Measur	ements/Cor	nponent Compilance
Com	pliance Description	Data Co	ompliance Description
No	Refuge 1 Length (In)	32.0 N/	A Gutter 1 Ponding?
Yes	Refuge 1 Width (In)	72.0 N/	A Gutter 1 Lip Ht (In)
Yes	Refuge 1 Slope (%)	0.5 N/	A Gutter 1 Slope (%)
Yes	Refuge 1 X Slope (%)	4.3 N/	A Gutter 1 X Slope (%)
N/A	Painted X Walk1?	No N/	A DWS 1 Provided?
N/A	X Walk 1 Direction	To S N/	A DWS 1 Contrast?
N/A	X Walk 1 Width (In)	N/A N/	A DWS 1 Length (In)
N/A	Road 1 Slope (%)	5.7 N/	A DWS 1 Full Width?
N/A	Road 1 X Slope (%)	4.0 N/	A DWS 1 Offset (In)
No	Refuge 2 Length (In)	32.0 N/	A Gutter 2 Ponding?
Yes	Refuge 2 Width (In)	72.0 N/	A Gutter 2 Lip Ht (In)
Yes	Refuge 2 Slope (%)	3.4 N/	A Gutter 2 Slope (%)
No	Refuge 2 X Slope (%)	5.3 N/	A Gutter 2 X Slope (%)
N/A	Painted X Walk2?	No N/	A DWS 2 Provided?
N/A	X Walk 2 Direction	To N N/	A DWS 2 Contrast?
N/A	X Walk 2 Width (In)	N/A N/	A DWS 2 Length (In)
N/A	Road 2 Slope (%)	5.4 N/	A DWS 2 Full Width?
N/A	Road 2 X Slope (%)	0.4 N/	A DWS 2 Offset (In)
N/A	Refuge 3 Length (in)	N/A N/	A Gutter 3 Ponding?
N/A	Refuge 3 Width (in)	N/A N/	A Gutter 3 Lip Ht (in)
N/A	Refuge 3 Slope (%)	N/A N/	A Gutter 3 Slope (%)
N/A	Refuge 3 XSlone (%)	N/A N/	A Gutter 3 XSlone (%)

Total Cost:

3000.00

Obstruction Type

N/A Surface Condition

N/A N/A N/A Refuge 3 XSlope (%) Gutter 3 XSlope (%) N/A Painted X Walk3? N/A DWS 3 Provided? N/A X Walk 3 Direction N/A N/A DWS 3 Contrast? N/A X Walk 3 Width (in) DWS 3 Length (in) N/A N/A N/A Road 3 Slope (%) N/A DWS 3 Full Width? N/A Road 3 XSlope (%) DWS 3 Offset (in) N/A N/A Any Obstructions? **N/A N/A** Storm Grate/Utility Hazard? N/A

N/A

Good

N/A Storm Grate/Utility Type





