


Access Compliance Report

Public Rights-of-Way

(Transit Stops)

Intersection ID: 10032790	Main Street: N_WENDOVER_RD	Cross Street: BEAL ST	Location: SE
ADA ID: 210885273854	Overall Compliance: N/A	Severity Score: 80	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

N/A

Surveyor Notes:

N/A

PROW/ADA:

N/A

CATS Stop ID: 45136
 CATS Stop Description: Wendover Rd & Beal St
 CATS Route ID: 39
 CATS Route Name: Eastway Drive

Total Cost: \$0.00

Compliance	Description	Data
N/A	Boarding Area	No
N/A	Boarding Area Width (in)	N/A
N/A	Boarding Area Length (in)	N/A
N/A	Boarding Area Slope %	N/A
N/A	Boarding Area XSlope %	N/A
N/A	PAR 1 Exist?	Yes
N/A	PAR 1 Width (in)	61.0
N/A	PAR 1 Slope %	0.7
N/A	PAR 1 XSlope %	0.6
N/A	PAR 1 XSlope Location	Perp
N/A	PAR 2 Exist?	No
N/A	PAR 2 Width (in)	N/A
N/A	PAR 2 Slope %	N/A
N/A	PAR 2 XSlope %	N/A
N/A	PAR 2 XSlope Location	N/A
N/A	Boarding Area Connected to PAR?	No
N/A	Road Slope %	0.4
N/A	Shelter	No
N/A	Clear Floor Space	No
N/A	Clear Floor Space Shelter	No
N/A	Clear Floor Space Width (in)	N/A
N/A	Clear Floor Space Length (in)	N/A
N/A	Clear Floor Space Slope %	N/A
N/A	Clear Floor Space XSlope %	N/A
N/A	Alcove Condition?	No
N/A	Transit Sign?	Yes
N/A	Transit Sign Height (in)	94.0
N/A	Bench?	No
N/A	Protruding Objects?	No

