


# Access Compliance Report

## Public Rights-of-Way

### (Transit Stops)

| Intersection ID: N/A                    | Main Street: S COLLEGE ST | Cross Street: E_STONEWALL_ST            | Location: NW |
|-----------------------------------------|---------------------------|-----------------------------------------|--------------|
| ADA ID: 665EE8B282A6                    | Overall Compliance: N/A   | Severity Score: 40                      |              |
| Codes/Mitigation Info/Possible Solution |                           | Field Measurements/Component Compliance |              |



Possible Solutions:

N/A

Surveyor Notes:

N/A

PROW/ADA:

N/A

CATS Stop ID: 45399

CATS Stop Description: College St & Stonewall St

CATS Route ID: 16, 5

CATS Route Name: Multiple

Total Cost: \$0.00

| Compliance | Description                     | Data  |
|------------|---------------------------------|-------|
| Yes        | Boarding Area                   | Yes   |
| Yes        | Boarding Area Width (in)        | 120.0 |
| Yes        | Boarding Area Length (in)       | 120.0 |
| Yes        | Boarding Area Slope %           | 0.9   |
| Yes        | Boarding Area XSlope %          | 0.1   |
| Yes        | PAR 1 Exist?                    | Yes   |
| Yes        | PAR 1 Width (in)                | 107.0 |
| Yes        | PAR 1 Slope %                   | 0.2   |
| Yes        | PAR 1 XSlope %                  | 0.6   |
| N/A        | PAR 1 XSlope Location           | Perp  |
| Yes        | PAR 2 Exist?                    | Yes   |
| Yes        | PAR 2 Width (in)                | 107.0 |
| Yes        | PAR 2 Slope %                   | 0.5   |
| Yes        | PAR 2 XSlope %                  | 1.4   |
| N/A        | PAR 2 XSlope Location           | Perp  |
| Yes        | Boarding Area Connected to PAR? | Yes   |
| N/A        | Road Slope %                    | 0.9   |
| N/A        | Shelter                         | No    |
| N/A        | Clear Floor Space               | No    |
| N/A        | Clear Floor Space Shelter       | No    |
| N/A        | Clear Floor Space Width (in)    | N/A   |
| N/A        | Clear Floor Space Length (in)   | N/A   |
| N/A        | Clear Floor Space Slope %       | N/A   |
| N/A        | Clear Floor Space XSlope %      | N/A   |
| N/A        | Alcove Condition?               | No    |
| Yes        | Transit Sign?                   | Yes   |
| Yes        | Transit Sign Height (in)        | 93.5  |
| N/A        | Bench?                          | No    |
| Yes        | Protruding Objects?             | No    |

