


# Access Compliance Report Public Rights-of-Way (Transit Stops)

|                          |                                   |                    |             |
|--------------------------|-----------------------------------|--------------------|-------------|
| Intersection ID: 1001921 | Main Street: PROSPERITY_CHURCH_RD | Cross Street: N/A  | Location: S |
| ADA ID: 78772EE14952     | Overall Compliance: No            | Severity Score: 45 |             |

| Codes/Mitigation Info/Possible Solution | Field Measurements/Component Compliance |
|-----------------------------------------|-----------------------------------------|
|-----------------------------------------|-----------------------------------------|



Possible Solutions:

**Remove & Replace Boarding Area.  
Remove & Replace Sidewalk To  
Boarding Area. Adjust Transit Stop  
Sign Height.**

Surveyor Notes:

**N/A**

PROW/ADA:

**302.7, 402.2, 810.2.2, 810.2.3,  
810.2.4, R302, R302.6, R308.1.1.1,  
R308.1.1.2, R402.3**

| Compliance | Description                     | Data |
|------------|---------------------------------|------|
| Yes        | Boarding Area                   | Yes  |
| Yes        | Boarding Area Width (in)        | 70.0 |
| No         | Boarding Area Length (in)       | 88.0 |
| Yes        | Boarding Area Slope %           | 1.9  |
| No         | Boarding Area XSlope %          | 2.5  |
| No         | PAR 1 Exist?                    | Yes  |
| Yes        | PAR 1 Width (in)                | 88.0 |
| No         | PAR 1 Slope %                   | 2.5  |
| Yes        | PAR 1 XSlope %                  | 1.9  |
| N/A        | PAR 1 XSlope Location           | Perp |
| N/A        | PAR 2 Exist?                    | No   |
| N/A        | PAR 2 Width (in)                | N/A  |
| N/A        | PAR 2 Slope %                   | N/A  |
| N/A        | PAR 2 XSlope %                  | N/A  |
| N/A        | PAR 2 XSlope Location           | N/A  |
| Yes        | Boarding Area Connected to PAR? | Yes  |
| N/A        | Road Slope %                    | 2.2  |
| N/A        | Shelter                         | No   |
| N/A        | Clear Floor Space               | No   |
| N/A        | Clear Floor Space Shelter       | No   |
| N/A        | Clear Floor Space Width (in)    | N/A  |
| N/A        | Clear Floor Space Length (in)   | N/A  |
| N/A        | Clear Floor Space Slope %       | N/A  |
| N/A        | Clear Floor Space XSlope %      | N/A  |
| N/A        | Alcove Condition?               | No   |
| Yes        | Transit Sign?                   | Yes  |
| No         | Transit Sign Height (in)        | 50.0 |
| N/A        | Bench?                          | No   |
| Yes        | Protruding Objects?             | No   |

CATS Stop ID: **46710**

CATS Stop Description: **Prosperity Church Rd & Katelyn Dr**

CATS Route ID: **59**

CATS Route Name: **North Meck Connector**

Total Cost: \$ **1650.00**

