


Access Compliance Report Public Rights-of-Way (Transit Stops)

Intersection ID: 12038	Main Street: E_8TH_ST	Cross Street: N_COLLEGE_ST	Location: S
ADA ID: DB88F9B50015	Overall Compliance: No	Severity Score: 35	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

Remove or Relocate Protruding Objects/Obstructions.

Surveyor Notes:

N/A

PROW/ADA:

N/A

CATS Stop ID: **25390**
 CATS Stop Description: **College St & 8th St**
 CATS Route ID: **40x, 46x, 52x, 64x, 65x, 74x**
 CATS Route Name: **Multiple**

Total Cost: \$ **2000.00**

Compliance	Description	Data
Yes	Boarding Area	Yes
Yes	Boarding Area Width (in)	60.0
Yes	Boarding Area Length (in)	108.0
Yes	Boarding Area Slope %	0.9
Yes	Boarding Area XSlope %	0.7
Yes	PAR 1 Exist?	Yes
Yes	PAR 1 Width (in)	92.0
Yes	PAR 1 Slope %	0.7
Yes	PAR 1 XSlope %	0.9
N/A	PAR 1 XSlope Location	Perp
Yes	PAR 2 Exist?	Yes
Yes	PAR 2 Width (in)	92.0
Yes	PAR 2 Slope %	0.5
Yes	PAR 2 XSlope %	1.9
N/A	PAR 2 XSlope Location	Perp
Yes	Boarding Area Connected to PAR?	Yes
N/A	Road Slope %	0.3
N/A	Shelter	No
N/A	Clear Floor Space	No
N/A	Clear Floor Space Shelter	No
N/A	Clear Floor Space Width (in)	N/A
N/A	Clear Floor Space Length (in)	N/A
N/A	Clear Floor Space Slope %	N/A
N/A	Clear Floor Space XSlope %	N/A
N/A	Alcove Condition?	No
Yes	Transit Sign?	Yes
Yes	Transit Sign Height (in)	92.5
N/A	Bench?	No
No	Protruding Objects?	Yes

