

Access Compliance Report Public Rights-of-Way (Transit Stops)

Intersection ID: 10012441	Main Street: PARKWOOD_AV	Cross Street: N/A	Location: N
ADA ID: E123911B2A31	Overall Compliance: No	Severity Score: 20	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

**Remove & Replace Boarding Area.
Remove & Replace Sidewalk To
Boarding Area.**

Surveyor Notes:

N/A

PROW/ADA:

**402.2, 810.2.3, 810.2.4, R302, R302.5,
R308.1.1.2**

Compliance	Description	Data
Yes	Boarding Area	Yes
Yes	Boarding Area Width (in)	60.0
Yes	Boarding Area Length (in)	114.0
No	Boarding Area Slope %	4.9
No	Boarding Area XSlope %	3.3
No	PAR 1 Exist?	Yes
Yes	PAR 1 Width (in)	60.0
Yes	PAR 1 Slope %	1.7
No	PAR 1 XSlope %	3.3
N/A	PAR 1 XSlope Location	Perp
Yes	PAR 2 Exist?	Yes
Yes	PAR 2 Width (in)	60.0
Yes	PAR 2 Slope %	0.5
Yes	PAR 2 XSlope %	2.0
N/A	PAR 2 XSlope Location	Perp
Yes	Boarding Area Connected to PAR?	Yes
N/A	Road Slope %	1.7
N/A	Shelter	Yes
Yes	Clear Floor Space	Yes
N/A	Clear Floor Space Shelter	Yes
Yes	Clear Floor Space Width (in)	66.0
Yes	Clear Floor Space Length (in)	65.0
Yes	Clear Floor Space Slope %	2.0
Yes	Clear Floor Space XSlope %	1.4
N/A	Alcove Condition?	No
Yes	Transit Sign?	Yes
Yes	Transit Sign Height (in)	82.5
N/A	Bench?	Yes
Yes	Protruding Objects?	No

CATS Stop ID: 21600

CATS Stop Description: **Parkwood Ave & The Plaza**

CATS Route ID: 4

CATS Route Name: **Belmont**

Total Cost: \$ 1450.00

