




Access Compliance Report  
Public Rights-of-Way  
(Accessible Street Parking)



|                                                                                   |              |              |                                         |                                                |
|-----------------------------------------------------------------------------------|--------------|--------------|-----------------------------------------|------------------------------------------------|
| Bounding Streets: AUTEN_ST, DUCKWORTH_AV, SUMTER_AV, WALNUT_AV, WESLEY_HEIGHTS_WY |              |              |                                         |                                                |
| ADA ID:                                                                           | 55F26036C099 | ParkingType: | Block Parking Counts                    | Overall Compliance: Yes    Severity Score: 0.0 |
| Codes/Mitigation Info/Possible Solution                                           |              |              | Field Measurements/Component Compliance |                                                |



Possible Solutions:

N/A


Surveyor Notes:

N/A

PROW/ADA:

N/A

| Compliance | Description             | Data |
|------------|-------------------------|------|
| N/A        | Total Spaces            | 11   |
| Yes        | Total Accessible Spaces | 1    |



Total Cost: \$ 0.00