

# Access Compliance Report

## Public Rights-of-Way

### (Accessible Street Parking)

Intersection ID: N/A	Main Street: E 8TH ST	Location: N/A
ADA ID: 0E453F21E56E	ParkingType: ParaPark	Overall Compliance: No
		Severity Score: 0.0
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance



Possible Solutions:


**Advise relocating to an area with maximum 2% slopes**

Surveyor Notes:

**N/A**

PROW/ADA:

**TBD**



Total Cost: \$ **\$0.00**

Compliance	Description	Data	Compliance	Description	Data
N/A	Parking Spot At End of Block?	Yes	Yes	Accessible Route?	Yes
Yes	Adjacent Sidewalk Width (in)	96.0	No	Access Aisle Marking?	No
No	Adjacent Sidewalk Slope (%)	4.8	N/A	Access Aisle Width (in)	65.0
No	Adjacent Sidewalk XSlope (%)	2.5	N/A	Access Aisle Length (in)	263.0
Yes	Adjacent Sidewalk Clear of Obstr.	Yes	N/A	Access Aisle Location	Side
	N/A	Parking Spot Width (in)		96.0	
	N/A	Parking Spot Length (in)		263.0	
	N/A	Van Accessible?		N/A	
	Yes	Curb Ramp?		Yes	
	N/A	Identification Sign?		N/A	
	N/A	Sign Height (in)		N/A	
	N/A	Vertical Clearance		N/A	
	N/A	Parking Meter?		N/A	
	N/A	Parking Meter Height (in)		N/A	
	N/A	Meter Operable Parts?		N/A	
	N/A	Meter Clear Space?		N/A	
	N/A	Meter Clear Space Slope (%)		N/A	
	N/A	Meter Clear Space XSlope (%)		N/A	
	N/A	Meter Forward Reach?		N/A	
	N/A	Meter Forward Reach (in)		N/A	
	N/A	Meter Parallel Reach?		N/A	
	N/A	Meter Parallel Reach (in)		N/A	

N/A	Parking Space/Access Aisle Slopes (%)							
	C Slope (%)	3.2	D Slope (%)	2.5	I Slope (%)	N/A	L Slope (%)	N/A
	B Slope (%)	3.9	E Slope (%)	3.7	H Slope (%)	N/A	K Slope (%)	N/A
	A Slope (%)	4.7	F Slope (%)	4.6	G Slope (%)	N/A	J Slope (%)	N/A
N/A	Parking Space/Access Aisle XSlopes (%)							
	C XSlope (%)	2.3	D XSlope (%)	5.0	I XSlope (%)	N/A	L XSlope (%)	N/A
	B XSlope (%)	2.0	E XSlope (%)	2.9	H XSlope (%)	N/A	K XSlope (%)	N/A
	A XSlope (%)	2.2	F XSlope (%)	2.8	G XSlope (%)	N/A	J XSlope (%)	N/A

