

Access Compliance Report

Public Rights-of-Way

(Accessible Street Parking)

Intersection ID: 13846	Main Street: CAMDEN_RD	Location: N/A
ADA ID: 15BE65640F54	ParkingType: ParaPark	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Severity Score: 0.0
		Field Measurements/Component Compliance



Possible Solutions:


Advise relocating to an area with maximum 2% slopes

Surveyor Notes:

N/A

PROW/ADA:

TBD



Total Cost: \$ \$0.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Parking Spot At End of Block?	Yes	Yes	Accessible Route?	Yes
Yes	Adjacent Sidewalk Width (in)	75.0	No	Access Aisle Marking?	No
No	Adjacent Sidewalk Slope (%)	4.0	N/A	Access Aisle Width (in)	N/A
No	Adjacent Sidewalk XSlope (%)	2.3	N/A	Access Aisle Length (in)	N/A
N/A	Adjacent Sidewalk Clear of Obstr.	N/A	N/A	Access Aisle Location	N/A
	N/A	Parking Spot Width (in)		74.0	
	N/A	Parking Spot Length (in)		257.5	
	N/A	Van Accessible?		N/A	
	No	Curb Ramp?		No	
	N/A	Identification Sign?		N/A	
	N/A	Sign Height (in)		N/A	
	N/A	Vertical Clearance		N/A	
	N/A	Parking Meter?		N/A	
	N/A	Parking Meter Height (in)		N/A	
	N/A	Meter Operable Parts?		N/A	
	N/A	Meter Clear Space?		N/A	
	N/A	Meter Clear Space Slope (%)		N/A	
	N/A	Meter Clear Space XSlope (%)		N/A	
	N/A	Meter Forward Reach?		N/A	
	N/A	Meter Forward Reach (in)		N/A	
	N/A	Meter Parallel Reach?		N/A	
	N/A	Meter Parallel Reach (in)		N/A	

N/A	Parking Space/Access Aisle Slopes (%)						
C Slope (%)	1.5	D Slope (%)	4.0	I Slope (%)	N/A	L Slope (%)	N/A
B Slope (%)	2.1	E Slope (%)	3.0	H Slope (%)	N/A	K Slope (%)	N/A
A Slope (%)	4.1	F Slope (%)	2.3	G Slope (%)	N/A	J Slope (%)	N/A
N/A	Parking Space/Access Aisle XSlopes (%)						
C XSlope (%)	3.8	D XSlope (%)	7.3	I XSlope (%)	N/A	L XSlope (%)	N/A
B XSlope (%)	4.5	E XSlope (%)	7.9	H XSlope (%)	N/A	K XSlope (%)	N/A
A XSlope (%)	4.8	F XSlope (%)	6.3	G XSlope (%)	N/A	J XSlope (%)	N/A

