

Access Compliance Report Public Rights-of-Way (Accessible Street Parking)



J XSlope (%)

N/A

5.6 F XSlope (%)

A XSlope (%)

3.6 G XSlope (%)

Intersection ID: 10031762 Main Street: MIDWAY PARK DR Location: N/A Overall Compliance: No **Severity Score:** ADA ID: 61B809BBA807 ParkingType: ParaPark 0.0

Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance Data Compliance Possible Solutions: Compliance Description Description Data No Yes N/A Parking Spot At End of Block? Accessible Route? Yes Advise relocating to an area with maximum 2% slopes Yes Adjacent Sidewalk Width (in) 129.0 No Access Aisle Marking? No Yes Adjacent Sidewalk Slope (%) 1.5 N/A Access Aisle Width (in) 61.0 Adjacent Sidewalk XSlope (%) 408.0 1.1 N/A Access Aisle Length (in) Yes Adjacent Sidewalk Clear of Obstr. No N/A Access Aisle Location Side No N/A Parking Spot Width (in) 80.0 Surveyor Notes: N/A Parking Spot Length (in) 403.0 N/A N/A Van Accessible? N/A Curb Ramp? Yes Yes N/A Identification Sign? N/A N/A Sign Height (in) N/A Vertical Clearance N/A N/A Parking Meter? N/A N/A PROW/ADA: N/A Parking Meter Height (in) N/A N/A Meter Operable Parts? N/A **TBD** N/A Meter Clear Space? N/A Meter Clear Space Slope (%) N/A N/A N/A Meter Clear Space XSlope (%) N/A D N/A Meter Forward Reach? N/A N/A Meter Forward Reach (in) N/A Meter Parallel Reach? N/A N/A \$0.00 Total Cost: N/A Meter Parallel Reach (in) N/A Parking Space/Access Aisle Slopes (%) N/A C Slope (%) **1.7** D Slope (%) **1.5** I Slope (%) N/A L Slope (%) N/A 1.6 E Slope (%) K Slope (%) B Slope (%) H Slope (%) N/A A Slope (%) **1.4** F Slope (%) 3.1 G Slope (%) N/A J Slope (%) N/A Parking Space/Access Aisle XSlopes (%) C XSlope (%) **4.6** D XSlope (%) I XSlope (%) L XSlope (%) N/A B XSlope (%) 4.7 E XSlope (%) H XSlope (%) K XSlope (%) N/A