


# Access Compliance Report

## Public Rights-of-Way

### (Accessible Street Parking)

Intersection ID: 10031919	Main Street: MOCKINGBIRD_LN	Location:	N/A
ADA ID: BDDFC852A5A1	ParkingType: ParaPark	Overall Compliance: No	Severity Score: 0.0
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

**Advise relocating to an area with maximum 2% slopes**

Surveyor Notes:


**N/A**

PROW/ADA:

**TBD**

Compliance	Description	Data	Compliance	Description	Data
N/A	Parking Spot At End of Block?	No	Yes	Accessible Route?	Yes
Yes	Adjacent Sidewalk Width (in)	94.0	No	Access Aisle Marking?	Yes
Yes	Adjacent Sidewalk Slope (%)	1.3	No	Access Aisle Width (in)	57.0
Yes	Adjacent Sidewalk XSlope (%)	1.2	Yes	Access Aisle Length (in)	260.0
Yes	Adjacent Sidewalk Clear of Obstr.	Yes	N/A	Access Aisle Location	Side
	N/A	Parking Spot Width (in)		87.0	
	N/A	Parking Spot Length (in)		260.0	
	N/A	Van Accessible?		N/A	
	Yes	Curb Ramp?		Yes	
	N/A	Identification Sign?		N/A	
	N/A	Sign Height (in)		N/A	
	N/A	Vertical Clearance		N/A	
	N/A	Parking Meter?		N/A	
	N/A	Parking Meter Height (in)		N/A	
	N/A	Meter Operable Parts?		N/A	
	N/A	Meter Clear Space?		N/A	
	N/A	Meter Clear Space Slope (%)		N/A	
	N/A	Meter Clear Space XSlope (%)		N/A	
	N/A	Meter Forward Reach?		N/A	
	N/A	Meter Forward Reach (in)		N/A	
	N/A	Meter Parallel Reach?		N/A	
	N/A	Meter Parallel Reach (in)		N/A	

Total Cost: \$ \$0.00



N/A	Parking Space/Access Aisle Slopes (%)							
	C Slope (%)	0.5	D Slope (%)	2.1	I Slope (%)	N/A	L Slope (%)	N/A
	B Slope (%)	1.4	E Slope (%)	1.0	H Slope (%)	N/A	K Slope (%)	N/A
	A Slope (%)	1.4	F Slope (%)	0.8	G Slope (%)	N/A	J Slope (%)	N/A
N/A	Parking Space/Access Aisle XSlopes (%)							
	C XSlope (%)	4.1	D XSlope (%)	0.0	I XSlope (%)	N/A	L XSlope (%)	N/A
	B XSlope (%)	1.3	E XSlope (%)	0.8	H XSlope (%)	N/A	K XSlope (%)	N/A
	A XSlope (%)	1.2	F XSlope (%)	0.2	G XSlope (%)	N/A	J XSlope (%)	N/A

