

Access Compliance Report Public Rights-of-Way (Accessible Street Parking)



Intersection ID: N/A Main Street: OLD PINEVILLE RD Location: N/A Overall Compliance: No **Severity Score: ADA ID: ED2E3118A35E** ParkingType: ParaPark 0.0

Field Measurements/Component Compliance Codes/Mitigation Info/Possible Solution Data Compliance Possible Solutions: Compliance Description Description Data Accessible Route? N/A Parking Spot At End of Block? No Yes Yes Advise relocating to an area with maximum 2% slopes No Adjacent Sidewalk Width (in) 47.0 No Access Aisle Marking? Yes No Adjacent Sidewalk Slope (%) 4.9 No Access Aisle Width (in) 52.0 Adjacent Sidewalk XSlope (%) 260.0 1.9 Yes Access Aisle Length (in) Yes Yes Adjacent Sidewalk Clear of Obstr. Yes N/A Access Aisle Location Side N/A Parking Spot Width (in) 104.0 Surveyor Notes: N/A Parking Spot Length (in) 260.0 N/A N/A Van Accessible? N/A Curb Ramp? No No N/A Identification Sign? N/A N/A Sign Height (in) N/A Vertical Clearance N/A N/A Parking Meter? N/A N/A PROW/ADA: N/A N/A Parking Meter Height (in) N/A Meter Operable Parts? N/A **TBD** N/A Meter Clear Space? N/A N/A Meter Clear Space Slope (%) N/A N/A Meter Clear Space XSlope (%) N/A D N/A Meter Forward Reach? N/A N/A Meter Forward Reach (in) N/A Meter Parallel Reach? N/A N/A \$0.00 Total Cost: N/A Meter Parallel Reach (in) N/A Parking Space/Access Aisle Slopes (%) N/A 4.3 D Slope (%) I Slope (%) C Slope (%) L Slope (%) N/A B Slope (%) K Slope (%) E Slope (%) H Slope (%) N/A A Slope (%) 3.1 F Slope (%) 3.9 G Slope (%) N/A J Slope (%) N/A Parking Space/Access Aisle XSlopes (%) C XSlope (%) 8.2 D XSlope (%) I XSlope (%) L XSlope (%) N/A

B XSlope (%)

A XSlope (%)

4.2 E XSlope (%)

3.7 F XSlope (%)

H XSlope (%)

3.3 G XSlope (%)

K XSlope (%)

J XSlope (%)

N/A

N/A