

# Access Compliance Report Public Rights-of-Way (RR Crossings)

|                                         |                        |                                         |
|-----------------------------------------|------------------------|-----------------------------------------|
| Intersection ID: 10025367               | Main Street: E_8TH_ST  | Location: N/A                           |
| ADA ID: 047D86E266B5                    | Overall Compliance: No | Severity Score: 0.0                     |
| Codes/Mitigation Info/Possible Solution |                        | Field Measurements/Component Compliance |



Possible Solutions:

**Remove & Replace Detectable  
Warning System. Provide Pedestrian  
Gate.**

Surveyor Notes:

**N/A**

PROW/ADA:

**R305.2.5**

| Compliance | Description         | Data  |
|------------|---------------------|-------|
| Yes        | DWS Provided?       | Yes   |
| Yes        | DWS Contrast?       | Yes   |
| Yes        | DWS Width (in)      | Yes   |
| Yes        | DWS Length (in)     | 24.0  |
| No         | DWS Offset (in)     | 71.0  |
| No         | Pedestrian Gate?    | No    |
| N/A        | DWS Outside Gate?   | No    |
| N/A        | Rail Type?          | N/A   |
| N/A        | Flangeway Gap (in)  | 2.5   |
| Yes        | Sidewalk Width (in) | 172.0 |

Total Cost: \$ 2800.00

