


# Access Compliance Report Public Rights-of-Way (RR Crossings)

Intersection ID: 10025367	Main Street: E_8TH_ST	Location: N/A
ADA ID: 13E8B578D41D	Overall Compliance: No	Severity Score: 0.0
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Detectable  
Warning System. Provide Pedestrian  
Gate.**

Surveyor Notes:

**N/A**

PROW/ADA:

**R305.2.5**

Compliance	Description	Data
Yes	DWS Provided?	Yes
Yes	DWS Contrast?	Yes
Yes	DWS Width (in)	Yes
Yes	DWS Length (in)	24.0
No	DWS Offset (in)	69.0
No	Pedestrian Gate?	No
N/A	DWS Outside Gate?	No
N/A	Rail Type?	N/A
N/A	Flangeway Gap (in)	3.0
Yes	Sidewalk Width (in)	109.0

Total Cost: \$ 2800.00

