


Access Compliance Report Public Rights-of-Way (RR Crossings)

Intersection ID: 10035790	Main Street: REMOUNT_RD	Location: N/A
ADA ID: 4968DD1CAD6F	Overall Compliance: No	Severity Score: 0.0
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Detectable Warning System. Provide Pedestrian Gate. Remove & Replace Walking Surface Adjacent to Rail.

Surveyor Notes:

N/A

PROW/ADA:

R302.7.4, R305.2.5

Compliance	Description	Data
Yes	DWS Provided?	Yes
Yes	DWS Contrast?	Yes
Yes	DWS Width (in)	Yes
Yes	DWS Length (in)	36.0
No	DWS Offset (in)	38.0
No	Pedestrian Gate?	No
N/A	DWS Outside Gate?	N/A
N/A	Rail Type?	LightRail
No	Flangeway Gap (in)	3.0
Yes	Sidewalk Width (in)	58.0

Total Cost: \$ 3200.00

