


# Access Compliance Report Public Rights-of-Way (RR Crossings)

Intersection ID: 10025543	Main Street: E_TRADE_ST	Location: N/A
ADA ID: 541A1CB50D28	Overall Compliance: No	Severity Score: 0.0
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance



Possible Solutions:

**Install Detectable Warning System.  
Provide Pedestrian Gate. Remove &  
Replace Walking Surface Adjacent  
to Rail.**

Surveyor Notes:

**RR IN MIDDLE OF STREET**

PROW/ADA:

**R208.1, R302.7.4, R305.2.5**

Compliance	Description	Data
No	DWS Provided?	No
N/A	DWS Contrast?	N/A
N/A	DWS Width (in)	N/A
N/A	DWS Length (in)	N/A
N/A	DWS Offset (in)	N/A
No	Pedestrian Gate?	No
N/A	DWS Outside Gate?	N/A
N/A	Rail Type?	LightRail
No	Flangeway Gap (in)	2.5
Yes	Sidewalk Width (in)	114.0

Total Cost: \$ 2635.00

