


Access Compliance Report Public Rights-of-Way (RR Crossings)

| | | |
|---|-------------------------|---|
| Intersection ID: 5600 | Main Street: N_TRYON_ST | Location: N/A |
| ADA ID: 63298004E671 | Overall Compliance: No | Severity Score: 0.0 |
| Codes/Mitigation Info/Possible Solution | | Field Measurements/Component Compliance |



Possible Solutions:

**Install Detectable Warning System.
Remove & Replace Walking Surface
Adjacent to Rail.**

Surveyor Notes:

N/A

PROW/ADA:

R208.1, R302.7.4

| Compliance | Description | Data |
|------------|---------------------|-----------|
| No | DWS Provided? | No |
| N/A | DWS Contrast? | N/A |
| N/A | DWS Width (in) | N/A |
| N/A | DWS Length (in) | N/A |
| N/A | DWS Offset (in) | 165.0 |
| Yes | Pedestrian Gate? | Yes |
| N/A | DWS Outside Gate? | Yes |
| N/A | Rail Type? | LightRail |
| No | Flangeway Gap (in) | 3.0 |
| Yes | Sidewalk Width (in) | 120.0 |

Total Cost: \$ 635.00

