


Access Compliance Report Public Rights-of-Way (RR Crossings)

Intersection ID: 10025333	Main Street: E_6TH_ST	Location: N/A
ADA ID: 64444D97013A	Overall Compliance: No	Severity Score: 0.0
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Detectable
Warning System. Provide Pedestrian
Gate. Remove & Replace Walking
Surface Adjacent to Rail.**

Surveyor Notes:

N/A

PROW/ADA:

R302.7.4, R305.2.5

Compliance	Description	Data
Yes	DWS Provided?	Yes
Yes	DWS Contrast?	Yes
Yes	DWS Width (in)	Yes
Yes	DWS Length (in)	32.0
No	DWS Offset (in)	24.0
No	Pedestrian Gate?	No
N/A	DWS Outside Gate?	N/A
N/A	Rail Type?	LightRail
No	Flangeway Gap (in)	2.5
Yes	Sidewalk Width (in)	118.0

Total Cost: \$ 3200.00

