


# Access Compliance Report Public Rights-of-Way (RR Crossings)

Intersection ID: 10040203	Main Street: TYVOLA_RD	Location: N/A
ADA ID: F5E00E3D62E5	Overall Compliance: No	Severity Score: 0.0
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance



Possible Solutions:

**Install Detectable Warning System.  
Provide Pedestrian Gate. Remove &  
Replace Walking Surface Adjacent  
to Rail.**

Surveyor Notes:

**N/A**

PROW/ADA:

**R208.1, R302.7.4, R305.2.5**

Compliance	Description	Data
No	DWS Provided?	No
N/A	DWS Contrast?	N/A
N/A	DWS Width (in)	N/A
N/A	DWS Length (in)	N/A
N/A	DWS Offset (in)	N/A
No	Pedestrian Gate?	No
N/A	DWS Outside Gate?	N/A
N/A	Rail Type?	Freight
No	Flangeway Gap (in)	3.0
Yes	Sidewalk Width (in)	71.0

Total Cost: \$ 2635.00

